

PRIORITY

Declassification Review by NGA/DoD

OUT56013

multi

P 220002Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 4801.

1965 JUN 22 00 33Z

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 122 WAS USED IN MISSION 8024 FLOWN ON 17 JUNE 1965.

PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

22 JUN 1965

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THERE IS A CREASE ALONG THE OUTBOARD EDGE OF THE
 FILM ON FRAMES 1021 THROUGH 1026. IRREGULAR, SHORT PLUS DENSITY
 STREAKS ARE NOTED NEAR THE INBOARD EDGE OF THE FILM ON FRAMES 1304
 THROUGH 1311 AND 2046 THROUGH 2048. FINE PLUS DENSITY STREAKS
 PARALLEL TO AND AT VARIOUS DISTANCES FROM THE FILM EDGES, OCCUR
 INTERMITTENTLY THROUGHOUT THE MISSION. SMALL AREAS OF FOG ARE
 PRESENT ON FRAMES 1225, 1443, 1446 AND 1447. THESE FOGGED
 AREAS PROTRUDE APPROXIMATELY 2.0" INTO THE FILM FROM THE OUTBOARD
 EDGE. HEAT SPLICES ARE MADE BETWEEN FRAMES 1018/1019, 1026/1027,
 1357/1358, 1366/1367, 1928/1929, 2435/2436 AND IN FRAME 1351. A
 MANUFACTURER'S PLICE IS MADE IN FRAME 1833. EXCESS PIGMENTS
 IN TITLING OF FRAMES 1358 THROUGH 1440 ALTERED THE FRAME NUMBERS TO
 AN EXTENT THAT MADE THEM DIFFICULT TO INTERPRET CORRECTLY. THE

COPIES RECEIVED <i>7</i>		
Cy No.	Office	Act.
<i>1</i>	File	
<i>2</i>	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
<i>3, 4</i>	TID	<input checked="" type="checkbox"/>
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

SECRET

GROUP 1
 Excluded from automatic
 downgrading and
 declassification

DIGITS 3, 8 AND 9 WERE PARTICULARLY AFFECTED.

C. 9L SIDE: A ROW OF MINUS DENSITY DOTS SPACED 1.70" APART OCCURS 1.55" FROM THE OUTBOARD EDGE OF THE FILM ON THE FIRST 66 FRAMES. FAINT, INTERMITTENT PRESSURE ROLLER CHATTER IS PRESENT ALONG THE OUTBOARD EDGE OF THE FILM FROM FRAME 481 THROUGH THE END OF THE MISSION. NUMEROUS, SHORT IRREGULAR PLUS DENSITY STREAKS ARE PRESENT NEAR THE INBOARD EDGE OF THE FILM ON FRAMES 2641 THROUGH 2717. A FEW RANDOM PLUS DENSITY STREAKS ARE NOTED ON FRAMES 1201 THROUGH 1440. A FINE, CONTINUOUS PLUS DENSITY STREAK 0.20" FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT ON FRAMES 1441 THROUGH 1680. ANOTHER FINE, CONTINUOUS PLUS DENSITY STREAK 0.10" FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT ON FRAMES 2161 THROUGH 2400. A MANUFACTURER'S SPLICE IS MADE IN FRAME 179.

D. BOTH SIDES: STATIC DISCHARGES ALONG BOTH FILM EDGES OCCUR INTERMITTENTLY THROUGHOUT. FRAMES ARE TITLED CONSECUTIVELY FROM 0001 THROUGH 2717.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THE MISSION.

3. POSITIVE:

- A. PI SUITABILITY IS GOOD.
- B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 30 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/