MANAGER STATE THE PROPERTY AND THE WARRINGS

		1		
		-2-	25	5 X 1
	Ship's Name	Percentage of Completion	Remarks	
	ereneng dan in depth offer (a high of front of requirem analysis	Not comm being asset		
		being asser		25X1
	Vessels		are not priority constructions.	٥٤١
	Percentage of (Com	Remarks	25)
alveg	e ships of 75-ton 1	ift capacity	mende sette. Et Siidel die filoso geste denned fladdingsversensien on versteinisch antikse, sich sild od diphelikusete.	
1	200	completed except for outfit items, e.g. tiles	r minor carrying out shakedown tex- runs	2
	80	refitted; some parts of super; tures lacking	struc-	
	55	refitted;	date of launching	25
		started		20
	40	started hull and appurtenance completed		
	40	hull and appurtenance	ces launching expected in the	
weidshid an mored ored, e torer arges rders	the vessel we completed 90 percess completed and accepts which had no porwas used a leavator to the upper learning in case they contained no pedo storage room, we had and had been refit	hull and appurtenant completed as reconditioned as a subsent as a tempode at extended from a tempode at the torpedes of a hit, the tempodes of the ship had four materials.	marine tender, but doubted that she scheduled. I Her forward section in the crew quarters. A large room a side to side that she its sides were not could not explode as, while being the adjoining room aft of side to side, stored explosive sted of U-shaped and T-shaped in propulsion engines, two on	2!
weidshi i an mored ored, e tor arges rders o por opell ird e	the vessel were completed 90 percess completed and accepts which had no porwas used a elevator to the upper land in case they contained no pedo storage room, were and had been refit to side and two on the ers.	hull and appurtenance completed as reconditioned as a subsent as a subsent as as sommodated a naval detail tholes and extended from a torpedo store. The rower deck. of a hit, the torpedoes confined and shelves consisted. The ship had four materials and shelves consisted. The ship had four materials and side, and two one main engine on to be built soon. yet connected.	marine tender, but doubted that she scheduled. I Her forward section in the crew quarters. A large room a side to side to side its sides were not could not explode as, while being the adjoining room aft of side to side, stored explosive ted of U-shaped and T-shaped in propulsion engines, two on propeller shafts with two screw each side was installed and the one engine which was	2 ² 2 5X1
wenidshi	the vessel we completed 90 percessompleted and accept which had no porwas used a elevator to the upple and in case, they contained no pedo storage room, we they and had been refit to side and two on the ers. In again. In again, which could ow the waterline.	hull and appurtenance completed as reconditioned as a subsent as a subsent as a subsent as a subsent as a tempodated a naval detail tholes and extended from a tempodo store. The roser deck. of a hit, the torpodoes complete charges. The hich did not extend from racks and shelves consisted. The ship had four material management and the shipyard would not be tested by Buckaumine defense equipment the galengine room. The ceiling and the cabins and mess.	marine tender, but doubted that she scheduled. Her forward section in the crew quarters. A large room is side to side to side its sides were not its sides were not ould not explode as, while being the adjoining room aft of side to side, stored explosive ited of U-shaped and T-shaped in propulsion engines, two on propeller shafts with two screw each side was installed and the one engine which was	

25**X**1

	SECRET		-
			25
Material st	III Needed for the records	TOR was in the floating dock for prioritioning of the ship included 6 tons of 80 kg of Sicromal pipes, all of 9, 10 and	m ·
			2.
sneets of 8	type and I ton of Sicroma	ion would be given a Russian name Sich I steel of 8 type were received for the	rana ir
ing of some	new pipelines, and the re-	underwent general overhaul including the placement and repair of damaged parts. I er ship and might be used as a troopship	he lay-
erre bae ru	Sig Dag a	Tread naval crow hall noise the best	p. when
sne was a G	erman ship.	at at her bows.	2
out of the quay. 1: was large liquid ward and aft	isting alternately to port s a special ship, put in for l containers like ter ends of the upper deck.	etween 1,500 and 1,750 millimeters high, the had not yet made shakedown runs and I and to starboard. Vessel repair ened to those used on tank cars, were on	was lifted ay alongside
scheduled to	b be built. Lists indicating the by the design office to	d documents for the construction of travers g the materials required for their construction, the material supply section. Edule for the procurement of material for the procurement of the procureme	were struction
	THE REAL PROPERTY AND PARTY AND PARTY AND PARTY AND PARTY AND PARTY.	SING CHAPTER CHAPTER OF THE PROPERTY OF THE PR	Topasta.
	second <u>Dekade</u>	third <u>Dekade</u>	
	second * \	second n	
	second n	first	,
	first	third n	,
	first	second e	
	third	first	
	second n	first #	
	second n		
for repairs of for continual Hydronalium a Sicronal tube Sicronal sheet	second " ection had to prepare list; on freighter, 75-ton lift; and giving the standard on I improvement of the consum sheets for repair of vessel es of 9, 10 and 12 type for ets and Sicromal steels ave by the Amerhanmer rolling	third of third. A committee resumption of each item. A committee resumption lists was formed. and Sicromal sheets, Sicromal stee of repair of KASTOR were bottlenecks. The children of the third of thir	el and 25 only
for repairs a for continual Hydronalium a Sicromal tube Sicromal shee manufactured	second " ection had to prepare list; on freighter, 75-ton lift; and giving the standard on I improvement of the consum sheets for repair of vessel es of 9, 10 and 12 type for ets and Sicromal steels ave by the Amerhanmer rolling	first a third a third a third a third a sindicating the material needed per unitable and trawler, and per 100,000 eastman assumption of each item. A committee resumption lists was formed. and Sicromal sheets, Sicromal steep repair of KASTOR were bottlenecks. The silable in Feet Correct was Sixty.	el and 25 only eta
for repairs a for continual Hydronalium a Sicromal tube Sicromal shee manufactured	second " section had to prepare list: on freighter, 75-ton lift; and giving the standard con i improvement of the consumption	third a third a sindicating the material needed per unitable and trawler, and per 100,000 eastment on of each item. A committee resumption lists was formed. and Sicromal sheets, Sicromal steed repair of KASTOR were bottlenecks. The silable in East Germany were 8 type sheet millibrates a previous attempt to produce Sicromal	el and 25 only