

20 April 1971

25X1A9a

MEMORANDUM FOR THE RECORD

SUBJECT: Mr. [redacted]'s Memo dated 5 April 1971:
Motorized Shelving at Army Map Service

25X1A5a1

25X1A9a

1. As suggested in Mr. [redacted]'s memo, Mr. Don Abbott, Army Topographic Command was contacted 20 April.

25X1A5a1

25X1A9a 2. Mr. Abbott was asked if he would elaborate on the problem they are having with the [redacted] installed at his facility.

3. Mr. Abbott indicated that the problem as mentioned in Mr. [redacted]'s memo was not in the gear ratio, or gear box, but was found to be in the chain pulley at one end of the system. Mr. Abbott stated that there was a popping or cracking noise when the chain was travelling in one direction. [redacted] was contacted and when he visited the jobsite found that the chain pulley on one end was not level with the pulley located at the motor drive. The problem was corrected by shimming the pulley assembly. Mr. Abbott stated that one section had been repaired to date and repair did remove the noises.

25X1A9a [redacted]

25X1A9a

25X1A6a

cc: Mr. [redacted] A&RC [redacted]

on

Copy to [redacted]

RAB

25X1A9a