Approved For Release 2008/07/09: CIA-RDP80-00926A009300120001-0 SEE BOTTOM OF PAGE FOR SPECIAL CONTROLS, IF ANY C-O-M-F-I-D-E-M-T-I-A-L INFORMATION REPORT National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelati PREPARED AND DISSEMINATED BY of which in any manner to an unauthorized per-CENTRAL INTELLIGENCE AGENCY son is prohibited by law. COUNTRY China SUBJECT DATE DISTRIBUTED Port Information: Heingkang (navigation aids, hydrographic data betting facilities, sederity measures, lack of bunkering facilities) 13 Dec 1956 3 SUPPLEMENT TO REPORT # THIS IS UNEVALUATED INFORMATION /THE OFFICE OF HAVAL INTELLIGENCE FURNISHED THE FOLLOWING INFORMATION TO CIA FOR IAC DISSEMINATION IN ACCORDANCE WITH PARAGRAPH 3 c OF NSCID #7 (DIO, 8ND No 167-56).7 Alphabetical Designators In connection with information contained herein, specific points of interest are referred to in this report by the following alphabetical designators: A. Vessel's berth B. Suction dredge line C. New channel D. Reclaimed area E. Chinese passenger ship F. Seaman's Club G. AA gun mounts Radio station Power station visited Hsingkang 3. Approaches and Pilot Data Vessel Prior to arrival at subject port, vessel received the following message from PEMAVICO, "Please advise again ETA Taku Bar local time. Enter Changshan Channel only. Attention marks (Red) in position 37 39 24W, 119 10 30E. Mavigate with precaution." Vessel anchored at Taku Bar Pilot and security guard arrived via small tug and boarded vessel 301430H. Pilot appeared to be middle-aged, spoke English, and performed his work efficiently. Pilotage at subject port is compulsory at all times. Vessel arrived at berth 301636M, position labeled designator A. Upon departure from subject port 071045M Feb 56, pilot and security guard boarded vessel at berth and conducted vessel to Taku Bar. Security guards departed with pilot 071227H. Cold weather and frequent log were encountered during call. Ice was present but not heavy enough to require the use of icebreakers. Highest temperature recorded was 60°F; the lowest was 13°F. Anchorage Vessel was required to anchor outside harbor at Taku Bar to reduce vessel's draft by 15 inches

ARMY C-O-H-F-I-D-E-H-T-I-A-L DISTRIBUTION STATE

301505E.

25X1

NOFORN

IMITED

IMITED:
Dissemination limited to full-time employees of CIA, AEC and FM; and, within State and Defense, to the intelligence components, other offices producing NIS elements, and higher echlons with their immediate supporting statis. Not to be disseminated to consultants, external projects or reserve personnel on about term active duty (excepting individuals who are normally full-time employees of CIA, AEC, FBI, State or Defense) unless the written permission of the originating affice has been obtained through the Assistant Director for Central Reference, CIA.

After sufficient reduction in draft, vessel got underway from anchorage at

NAVY review completed.

C-O-W-Y-I-D-E-N-T-I-A-L

- 2 -

Marbor
allowed but vessel had to reduce draft to 25.6 feet before entering harbor. suction dredge line at east end of pier 41 at position labeled designator B. A new channel, labeled designator C, which connects the harbor and the river is now in use.
Controls A 15-mam boarding party, including the agent, security guards, a bealth officer, immigration and customs officers, and harbor superintendent, boarded the vessel 292200M at Taku Bar and remained aboard until 300130M. The boarding party divided into four groups and searched forward, aft, midships, and the engine room. One crew member accompanied each inspection team. Radio equipment, personal firearms, binoculars, radar, cameras, flares, and seattant were placed under seal. The crew was mustered and seaman's books were inspected. Two surveillance guards remained aboard until the vessel reached beath. After arrival at berth one guard was stationed at the gangway of the vessel and one guard was stationed at the gate to the dock area. Both guards were armed with machine guas and checked shore passes of all crew members going ashore. Bach crew member was given a shore pass written in Chinese which showed his seaman's number. Haval patrol craft patrolled the anchorage area; these craft used searchlights at night and had one machine gum mount forward. Frior to departure from port, a boarding party boarded the vessel 070840M Fab 56 and remained aboard until 071040M. Two security guards remained aboard the vessel with the outgoing pilot, removed seals from all items under seal, then departed with pilot.
Harbor Craft Two small motor tugs assisted vessel in berthing and departing from harbor. The lighter to which vessel discharged cargo had a full cargo capacity of 600 tons and was equipped with a steam lift. No other harbor craft were observed except surveillance patrol craft.
Vessel's berth was alongside a concrete quay 2500 feet in largth which could accommodate five vessels. The east end of this quay is used for loading coal; this area was being dredged as noted in paragraph 5. A sketch of the quay is labeled figure 8-a. No cranes or other handling facilities were present on quay. At low water the vessel's main deck was 12 feet above the that apron. Five gangs of stevedores - 13 men to each gang - worked during each of three sight-hour shifts. All ages of males were employed with good profitedency.
Inspectors tested the water aboard ship before vessel took on water. Both drinking and boiler water were delivered by hose. Vessel's agent indicated that there was a shortage of yower in the area.
Construction area labeled designator D has been filled in and is now occupied by new office buildings. All other buildings in the area appeared to be relatively new.

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN NO DISSEM ABROAD

LIMITED

25X1

25X1 25X1

25X1

25X1

25X1 25X1

25X1

25**X**1

25X1

25X1

25X1

C-O-N-F-I-D-E-N-T-I-A-L

- 3 -

15. Merchant Vessels

25**X**1

25X1

25X1

several Chinese freighters traveling in and out of area at various times. Due to heavy fog about 5 Feb 56 a 500-ton Chinese passenger ship, labeled designator E, passed via the new channel to the river.

- Shore activities All crew members were allowed ashore but were restricted to the downtown area and to the Seaman's Club. The Seaman's Club, labeled designation F, is located a short distance from the gate to the dock area. Only a small number of the crew went ashore due to poor weather conditions and lack of entertainment available. The vessel's agent remained aboard ship during cargo discharging operations except that he occasionally called for a US-built jeep and went ashore for a very short time. The agent ate and slept aboard the vessel.
- Niscellaneous The people encountered at subject port appeared to be afraid to talk and impressed with the ruling that school attendance was compulsory. Reports indicated that everyone had to attend classes for at least two hours per week. Some of the stevedores were compelled to take time off from handling the ship's cargo to attend classes. No anti-Communist feeling was noticed except that the agent stated that it took too much "red tape" to get things dome.

 a guard tower with an AA gun mount at position labeled designator G, an area which is under water at high tide. A radio station with 10 masts was sighted at position labeled designator H. An electric power station was located at position labeled designator I. Sanitation and health conditions were good as far as known.

- end =

CEU.

C-O-W-F-I-D-E-M-T-I-A-L

HOPORE

NO DISSIM ABROAD

LIMITED