

SEC ZERO FIVE TWO

Approved For Release 2000/09/14 : CIA-RDP89B00551R000800130016-2

25X1A 25X1A

PRITY [REDACTED] CITE [REDACTED] NINE ZERO NINE THREE

25X1A

20
59
13
22
ash

4131

REF MISSION FOUR ONE THREE ONE

25X1A

1. [REDACTED] TWO EIGHT MALFUNCTION DUE TO BLOWN FUSE IN NEGATIVE THREE VOLT SUPPLY OF VIDO PROCESSING UNIT. FUSE HAS BEEN REPLACED AND NORMAL OPERATION NOTED ON POST FLIGHT TESTS.

2. FURTHER CHECKS INDICATE RAW VIDO WAS RECORDED, STARTING THREE MINUTES AFTER TARGET TIME, WHEN [REDACTED] OPERATED

25X1A

[REDACTED] TWO EIGHT IN MANUAL MODE. LOCAL ANALYSIS UNABLE DETERMINE IF TAKE OF ANY VALUE. TAKE HAS BEEN DUPLICATED.

3. IN ADDITION, "PAPA" BAND AND "SIERRA" BAND WAS FLOWN DURING MISSION. TAKE SUCCESSFUL AND DUPLICATED.

4. ADVISE DISPOSITION REQUIRED FOR TAKE.

25X1A

CFN: [REDACTED] BLOWN FUSE NEGATIVE VOLT VIDO RAW VIDO [REDACTED]

[REDACTED] MANUAL MODE UNABLE "P" BAND AND "S" BAND.