

Ref ADIC. 0813 / Ref Adic 07

16 July

Del Rio # 1 Accident

- a) Moisture in lines.
- b) Kinks in O₂ hoses
- c) auto lap belt required excessive gas pressure for release

A+B are resultant from inadequate vigilance on part of P.E. section.

C Manufacturer + maintenance responsibility.

Acc. investigation incomplete as yet.