Approved For Release 2000/04/18 : CIA-RDP89B00551R[redacted]

25X1A

25X1A

[redacted]

25X1A

OPIM [redacted] CITE [redacted] 1908

25X1A

[redacted] 1705Z

WN00604

REFERENCE MISSION A-1010 APRIL 10, 56 SPECIFIC CAUSE FOR FUEL PUMP FAILURE DUE TO STEEL CHIP ENTERING PUMP CAUSING TO JAM. DURATION OF FLIGHT 2:55 HOURS.

25X1A

CFN: 453 1908 [redacted] 1705Z A-1010 10 56 2:55

Approved For Release 2000/04/18 : CIA-RDP89B00551R000600080003-4

BT