Sanitized Copy Approved for Release 2010/02/03 : CIA-RDP78B04558A000100230041-1

TOP SECRET

[redacted]

OUT56379

1965 AUG 6 21 18Z

T O P S E C R E T 062055Z

PRIORITY [redacted] 5152

25X1

IDEALIST

ATTENTION [redacted]

25X1

09 AUG 1965

COPIES RECEIVED 7

Dy No.	Office	Act.
2	File	
	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	[illegible]	

SUBJECT EVALUATION OF MISSION C405C

1. CAMERA B 8 WAS USED IN MISSION C405C FLOWN ON 21 JULY 1965. PROCESSING WAS ACCOMPLISHED BY EASTMAN KODAK.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS FAIR TO GOOD AND RESOLUTION IS GOOD.

B. 9R SIDE: ROLLER CHATTER AND EDGE STATIC ARE PRESENT ON BOTH SIDES FROM THE BEGINNING TO THE END OF THE MISSION. A BAND OF FOG 1.8" WIDE IS EVIDENT ON THE INBOARD EDGE. FOG ALSO APPEARS IN FRAME 833 ON THE INBOARD EDGE AND IN FRAME 1083 ALONG THE OUTBOARD EDGE. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 43/44, 176/177, 182/183, 309/310, 442/443, 463/464, 575/576, 708/709, 841/842, 872/873, 974/975 AND 1107/1108. A MANUFACTURING SPLICE LOCATED IN FRAME 137 IS ACCOMPANIED BY ASSOCIATED FOG.

C. 9L SIDE: A MINUS DENSITY STREAK ON THE OUTBOARD EDGE IS FIRST NOTED OF FRAME 401 AND CONTINUES THROUGH THE MISSION. THERE IS A BAND OF FOG 0.7" WIDE ON THE OUTBOARD EDGE OF FRAMES 725 THROUGH 732. SLIGHT EMULSION LIFTS, ABRASIONS AND CREASES OCCURE ON THE INBOARD EDGE OF FRAMES 932 THROUGH 941.

D. THE LAST TITLED FRAME IS 1184.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

[redacted]

GROUP 1
Excluded from automatic downgrading and declassification

25X1

TOP SECRET

Sanitized Copy Approved for Release 2010/02/03 : CIA-RDP78B04558A000100230041-1

Sanitized Copy Approved for Release 2010/02/03 : CIA-RDP78B04558A000100230041-1

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUD COVER OR HAZE OBSTRUCTED OR DEGRADED APPROXIMATELY 15 PERCENT OF THE MISSION.

T O P S E C R E T

/END OF MESSAGE/

Sanitized Copy Approved for Release 2010/02/03 : CIA-RDP78B04558A000100230041-1