Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080120-0

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11002

RECEIVED FROM

DATE REC'D. 1-23-57
P.O. NO.
VENDOR PACKING SLIP NO.

FILE # 9

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	22050	0	0	00	00			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
7	732624-1 BRACKET RESISTOR	7		
	SHIP MEMO 85875			

RECEIVED BY [illegible] INSPECTED BY [illegible] DATE 1/24/57 REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11004

RECEIVED FROM

DATE REC'D. 1-23-57
P.O. NO.
VENDOR PACKING SLIP NO.

FILE # 9

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	20007	0	0	00	00			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
15	738297 BOX CONTAINER SWITCH ASS'Y	15		
	SHIP MEMO 85886			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080120-0

RECEIVED BY [illegible] INSPECTED BY [illegible] DATE 1/24/57 REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1069