Approved For Release 2000/05/31 : CIA-RDP89B00551R000600040014-6

1006

ILLEGIB

[redacted]

(There was no Camera 1 coverage for this flight.)

Print received for all coverage for 2, 3, 4, and 5 cameras, quality poor.

Remarks:

Camera No. 2

1. Splices. no good (used only for leaders)
2. ~~Numerous~~ Occassional pinholes throughout
3. Counter not working
4. Negative very flat, and poor contrast, not always due to haze.
5. Prints, in ~~some~~ most cases, did not reproduce detail present on negative.
6. [illegible] operated satisfactorily

Camera No. 3

1. Splices. ~~no good.~~ unsatisfactory (didnt hold)
2. ~~Numerous~~ Occasional pinholes and scratches.
3. Counter not working.
4. Quality good
4. Clock ~~OK~~ operated satisfactorily.
5. Prints, in ~~some~~ most cases, did not reproduce detail present on negatives.
6. Fiducial marks reversed.

Counter was not readable on most of the negatives and on none of the prints

Approved For Release 2000/05/31 : CIA-RDP89B00551R000600040014-6

Approved For Release 2000/05/31 : CIA-RDP89B00551R000600040014-6

Mission 1006

Camera No 4

1. Splices ~~not good~~ unsatisfactory
2. Counter and clock not working.
3. ~~Numerous~~ Occasional pinholes throughout.
4. Negative very flat, and poor contrast, not alway due to haze.
5. Print in ~~some~~ most case, did not reproduce detail present on negative.

Camera No 5:

1. Only used in vertical position.
2. ~~Splices not good.~~
2 3. Clock and counter not printing well
3 ~~4. Counter " " "~~
3 5. Low contrast.
4 6. Black streaks and pinholes.

Approved For Release 2000/05/31 : CIA-RDP89B00551R000600040014-6