SECRET

PRIORITY

OUT52544

P 302210Z
FM CIA WASHDC
TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB
RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA
RUCVAB/2D RTS, BARKSDALE AFB, LA
RUEAHQ/DIAXX
RUECYG/NAVY PIC
RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF
RUWGAA/2AF, BARKSDALE AFB, LA
DA GRNC
BT
S E C R E T   CITE CIA-Z-1095

31 DEC 1963

CJS

Grace (File)

15TH AF (FOR DI), SAC (FOR DIM, GOLDEN TREE, DOCR, DM4) 2D AF

(FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 8 WAS USED IN MISSION 3803 FLOWN ON 29 DECEMBER

1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THE FIRST 26 FRAMES ARE CRIMPED ALONG THE

INBOARD EDGE. THERE IS A MANUFACTURER'S SPLICE IN FRAME 1119

AND FRAMES 1120 THROUGH 1123 CONTAIN NUMEROUS BLISTERS AND PINHOLES.

A REPAIRED TEAR IS PRESENT IN FRAME 299 ADJACENT TO THE TAIL IDENT

AND ANOTHER REPAIRED TEAR IS PRESENT IN FRAMES 2705/2706.

THERE ARE HEAT SPLICES BETWEEN FRAMES 1380/1381, 2194/2195 AND

2707/2708.

C. 9L SIDE: PLUS DENSITY STREAKS .10" FROM AND PARALLEL

TO THE INBOARD EDGE AND 4.3" FROM AND PARALLEL TO THE OUTBOARD

EDGE ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. MINUS

DENSITY STREAKS AT AND PARALLEL TO THE INBOARD EDGE AND 4.1" FROM

SECRET

SECRET

AND PARALLEL TO THE OUTBOARD EDGE OCCUR INTERMITTENTLY FROM HEAD

TO TAIL. FRAMES 1220 AND 1554 CONTAIN MANUFACTURER'S SPLICES

AND ASSOCIATED MINUS DENSITY SPOTS.

D. THERE WERE NO CAMERA MALFUNCTIONS OR PROCESSING

ANOMALIES OTHER THAN THE USUAL MINOR PROCESSING STREAKS. THE

IMAGERY IN A FEW OF THE FRAMES ARE SMEARED DUE TO VEHICLE ROLL.

EXAMPLES: FRAMES 26 AND 1665. THE FIRST FRAME IS TITLED 0000

AND THE LAST FRAME IS TITLED 2969.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD. THE PRINTING AND PROCESSING

OF THE PRINTS ARE GOOD.

B. CLOUDS COVER 80-85 PER CENT OF THE MISSION. SCP-1.

S E C R E T

-END OF MESSAGE-

(ALSO PASSED TO CIA WATCH (CGS))