TOP SECRET

"KICKOFF"

CONTROL CENTER

SCHEDULE OF EVENTS

Book	ACTION	ZULU	WASHINGTON, D. C. (DIST)	
✓ 1.	Pre-Alert weather briefing	X-2/2200Z	1800 EDST	N/R
25X1A ✓ 2.		X-2/2300Z	1900 EDST	N/R
	A. Direct support aircraft Depart X-1/1200Z for Laughlin AFB			R
	B. Commence 24 hour commo capability at this time			
* ✓ 3.	Alert weather briefing	X-1/0900Z	0500 EDST	N/R
25X1A ✓ 4.	Support aircraft depart [ ]	X-1/1200Z	0800 EDST	N/R
25X1A ✓ 5.		X-1/1300Z	0900 EDST	N/R
	A. C-54 depart, ETA Laughlin AFB			
✓ 6.	Support aircraft arrive Laughlin	X-1/1800Z	1400 EDST	N/R
✓ 7.	Telephone from Laughlin AFB	X-1/1900Z	1500 EDST	N/R
	A. Support ATA, in place			
	B. Obtain Laughlin telephone number			
* ✓ 8.	Mission Plan Weather Briefing	X-1/2200Z	1800 EDST	✓
✓ 9.	Telephone to Laughlin	X-1/2300Z	1900 EDST	✓
25X1A	A. Give [ ] Info 25X1A			
✓ 10.		X/0000Z	2000 EDST	N/R
25X1A 25X1A	A. Direct mission U-2 to depart [ ] for Laughlin AFB at X/0300Z. Send Hqs [ ] with ETA Laughlin AFB.			
25X1A 11.	Mission U-2 departs [ ]	X/0300Z	2300 EDST	N/R
25X1A 12.	[ ] from [ ] U-2 dept message - ETA Laughlin AFB	X/0400Z	0000 EDST	N/R

TOP SECRET

	ACTION	ZULU	WASHINGTON, D. C. (DIST)	
✓ 13.	Telephone to Laughlin - Give U-2 ETA	X/0500Z	0100 EDST	N/R
*✓ 14.	GO-NO-GO Weather briefing	X/0530Z	0130 EDST	✓
✓ 15.	U-2 arrives Laughlin AFB	X/0600	0200 EDST	N/R
✓ 16.	Telephone to Laughlin	X/0630Z	0230 EDST	✓
	A. Give GO weather info			
	B. Get ATA U-2 and Mx status			
25X1A ✓ 17.	[ ]	X/0700Z	0300 EDST	N/R
	A. U-2 arrival Laughlin and Mx status MAINT			
✓ 18.	Mission U-2 departs on mission	X/1000Z	0600 EDST	✓
✓ 19.	Telephone from Laughlin AFB	Z/1030Z	0630 EDST	
	A. ATD mission U-2			
	B. ETA mission U-2			
25X1A ✓ 20.	[ ]	X/1100Z	0700 EDST	✓
	A. Mission dept message, ETA			
N/R 21.	Telephone to Laughlin AFB	X/1800Z	1400 EDST	
	A. Return ferry weather			
22.	Mission U-2 arrives Laughlin	X/1930Z	1530 EDST	
25X1A 23.	Telephone from Laughlin AFB	X/2000Z	1600 EDST	
	A. ATA mission U-2			
25X1A ✓ 24.	[ ]	X/2030Z	1630 EDST	
	A. Mission U-2 arrival message			
25X1A 25.	U-2 dept Laughlin for [ ]	X/2130Z	1730 EDST	

25X1A

mission down re-schedul... TOP SECRET

for mis...

ACTION		ZULU	WASHINGTON, D. C. (DST)
—— 26.	Telephone from Laughlin	X/2200Z	1600 EDST
25X1A	A. U-2 dept info, ETA [ ]		
25X1A	B. ETD support aircraft ETA [ ]		
25X1A 27.	[ ]	X/2230Z	1830 EDST
25X1A	A. U-2 dept message, ETA [ ]		
25X1A	B. Support aircraft ETD, [ ]		
25X1A 28.	U-2 arrives [ ]	X+1/0030Z	2030 EDST
25X1A 29.	[ ] U-2 arrive	X+1/0100Z	2100 EDST
30.	Support aircraft dept Laughlin AFB	X+1/0130Z	2130 EDST
31.	Support aircraft arrives	X+1/0730Z	0330 EDST
25X1A	[ ]		
25X1A 32.	[ ]	X+1/0800Z	0400 EDST
	A. ATA support aircraft		
	B. ETA C-54 Rochester, N. Y.		
33.	Telephone from C-54 commander enroute Rochester, N. Y.		
	A. Firm ETA Rochester		

DEL RIO STAGING

"KICKOFF"

MISSION T/O - X/1000Z

WEATHER BRIEFING

1. Alert	X-2/2200Z	1800 EDST
2. Mission Plan	X-1/2200Z	1800 EDST
3. GO-NO-GO	X/0530Z	0130 EDST

        Route: VD: X/1000Z - 2000Z

        TRML : VD: X/1000Z - 1200Z - Laughlin AFB

          : VD: X/1830Z - 2030Z - Laughlin AFB

        ALT : VD: X/1230Z - 1630Z

                  X/1230Z - 1630Z

                  X/1230Z - 1630Z

                  X/1230Z - 1630Z

25X1A

25X1A

4. Ferry weather arrive   X-1/2230Z   1830 EDST

        Route: VD: X/0300Z - 0700Z

        TRML : VD: X/0300Z - 0500Z   25X1A

                X/0530Z - 0730Z - Laughlin AFB

5. Ferry weather arrive Headquarters: X/1700Z   1300 EDST

        Route: VD: X/2130Z - X+1/0130Z

        TRML : VD: X/2130Z - 2330Z - Laughlin AFB

                X+1/0000Z - 0200Z -   25X1A