

**SECRET**

**PRIORITY**

OUT 51858

P 132010Z

1963 SEP 13 22 29Z

16 SEP 1963

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF

RUWGAA/2D RTS, BARKSDALE AFB, LA

RUWGAA/2AF, BARKSDALE AFB, LA

DA GRNC

BT

**SECRET**

CITE CIA-Z-883

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM 4), 2D AF (FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 11 WAS USED IN MISSION 3719 FLOWN ON 12 SEPTEMBER 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: FOREIGN MATTER (INSECTS) ARE PRESENT ON FRAMES 191, 192 AND 193. SEVERE POST PROCESSING LONGITUDINAL SCRATCHES RUN THROUGH THE CENTER OF FRAMES 227 AND 228.
- C. 9L SIDE: THERE IS A CHEMICAL STAIN ON FRAME 053, AND A MANUFACTURING SPLICE ON FRAME 897. THE TWO FRAMES FOLLOWING THE HEAT SPLICE (898 AND 899) CONTAIN PINHOLES AND ARE CREASED.

Declassification Review by NGA/DoD

**SECRET**

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

D. BOTH SIDES: THERE ARE PROCESSING STREAKS THROUGHOUT. THE SHUTTER FAILED TO OPEN ON FRAME 1501. THE TOTAL NUMBER OF TITLED FRAMES IS 1521; HOWEVER, THE DATA SHEET INDICATES THAT THERE SHOULD BE A TOTAL OF 2,444 FRAMES.

E. BECAUSE OF THE DISCREPANCY IN THE TOTAL NUMBER OF FRAMES, IT IS POSSIBLE THAT A CAMERA MALFUNCTION OCCURRED. OTHER THAN CONTINUOUS PROCESSING STREAKS, THERE WERE NO SERIOUS PROCESSING PROBLEMS NOTED.

3. POSITIVE:

A. PI SUITABILITY WAS GOOD WHERE WEATHER PERMITTED. THE PRINTS OF PART 6, FRAMES 1500 TO 1521, WERE NOT RECEIVED.

B. CLOUDS MASKED ABOUT 90 PERCENT OF THE TAKE.

S E C R E T

END OF MESSAGE

(ABOVE MESSAGE ALSO PASSED TO CIA WATHH (CGS))

1