	• SECRET	2002/09/0	<u>₹₽'₹0₽</u>	EDENTIAL 5278B04747A002600	0010024-7 🔲 UNCLA	SSIFIED		
1	CONTRACT INSPECTIO			CONTRACT NO.	TASK NO.	25X1		
	TO:							
				26 May 1966				
	CONTRACT ADMINISTRATION BRANCH/PD/OL	& SETTL	EMENT		· (If final, so state)			
				ESTIMATED COMPLETION	DATE			
				New Complete				
	NAME OF CONTRACTOR		r,		***			
<u></u>					•	25X1/		
	TYPE OF COMMODITY OR SERVICE							
•	F.I. Change Detect	or Proto	tу р е			1.4		
	THE CONTRACTOR IS ON SCHEDULE			THE CONTRACTOR WILL I	PROBABLY REMAIN WITHIN	ALLOCATED		
	YES] NO		FUNDS YES NO	IF ANSWER IS "NO" ADV	ISE REC.		
	PER CENT OF WORK COMPLETED -	Y6		REVERSE HEREOF. IF I	KNOWN, INDICATE MAGNITU	DE OF AD-		
	PER CENT OF FUNDS EXPENDED . 10	%		DITTONAL FONDS INVOL	VED.			
:	HAS AN INTEDIM DEPORT FIL	NAL DEPORT	BROTOTVE					
	HAS AN INTERIM REPORT. FINAL REPORT. PROTOTYPE. OR OTHER END ITEM BEEN RECEIVED FROM THE CONTRACTOR DURING THE PERIOD? A YES NO (If yes, give details on reverse side.)							
	HAS GOVERNMENT-OWNED PROPERTY BEEN DELIVERED TO CONTRACTOR DURING THIS PERIOD? YES (If yes, indicate items, quantity, and cost on reverse side.)							
	I NCENT I VES							
	IS THIS AN INCENTIVE CONTRACT IF YES, CHECK TYPE	YES	🟝 ио	NOTE:	001111111111111111111111111111111111111			
	USE REVERSE SIDE FOR COMMENTS. COST PERFORMANCE DELIVERY FINAL REPORT MUST CONTAIN INCENTIVE EVALUATION.							
	OVERALL PERFORMANCE OF CONTRACTOR							
	1. OUTSTANDING	Can.	···					
	o o o o o o o o o o o o o o o o o o o		BOVE AVERA	AGE 5. BELOW	AVERAGE 7. UNSAT	ISFACTOR		
	2. EXCELLENT 4. AVERAGE 6. BARELY ADEQUATE IF OVERALL PERFORMANCE OF CONTRACTOR IS UNSATISFACTORY OR BARELY ADEQUATE, INDICATE REASONS ON REVERSE SIDE.							
	RECOMMENDED ACTION							
class Rev	view by NHMANT DODAS PROGRAMMED WITHHOLD PAYMENT PENDING SATISFACTORY PERFORMANCE							
:								
ı	TERMINATE			OTHER (Specify)	Contract Settlem	ent		
	IF TERMINATION IS RECOMMENDED OR IF THIS IS A FINAL REPORT PUT COMMENTS ON REVERSE IN NARRATIVE							
	FORM ON CONTRACTOR'S PERFORMANCE AND CERTIFY THAT ALL DELIVERABLE ITEMS UNDER THE CONTRACT HAVE BEEN RECEIVED. THESE INCLUDE, WHERE APPLICABLE, THE FOLLOWING:							
	ITEM	REC'D	DOES NOT	ITEM	REC'D	DOES NOT		
	PROTOTYPES	X	<u> </u>	MANUALS	x			
	DRAWINGS AND SPECIFICATIONS	X		FINAL REPORT	х	<u> </u>		
	PRODUCTION AND/OR OTHER END ITEMS		925	SPECIAL TOOLING	X	-		
			X	OTHER GOVERNMENT PROPE	RTY # (See	Revers		
	DATE OF LAST CONTACT WITH CONTRACTOR	,			·			
	DATE OF LAST CONTACT WITH CONTRACTOR							
				DIVISION		ΣV1 Λ		
						5X1A		
	11-12 May 1966			DIVISION		5X1A 5X1A		

Approved For Release 20020903: CIA-RDP/880478/ APREASO0010024-7 FINAL 25X1 On 11 May 1966 Release 20020903: CIA-RDP/880478/ APREASO0010024-7 Release 200208 Five (5) copies of the Maintenance Manual for the F.I. Change Detector Prototype. These manuals constitute final delivery of all items agentified in the contract. However, the attached copy of a letter in the R&DC project file indicates that several deliverable items may still be held by the contractor. This should be determined during contract sottlement. Stild to the AIF Force; however, this action is not officially documented in the F&DC project file. Standard arried back to the interpretation of the property of this Agency's contracts. This CRT had sustained during another of this Agency's contracts. This CRT had sustained damage and was not useable on the Change Detector. The overall performance of this contractor has been above average the quality of workmanship performed was highly satisfactory. The company has in all cases been responsive to customers requests. The delay in final acceptance and failure to meet some of the design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	
On 11 May 1965 five (5) copies of the Maintenance Manual for the F.I. Change Detector Prototype. These manuals constitute final delivery of all items specified in the contract. However, the attached copy of a letter in the Pads project file indicates that several deliverable items may still be held by the contractor. This should be determined during contract sottlement. Stated that "some of the breadboard components were sold to the Air Force;" however, this action is not officially documented in the Pads project file play has been about a carried back to the one Cuthode Ray Tube type C5816 for use on another of this Agency's contracts. This CRT had sustained damage and was not useable on the Change Detector. The overall performance of this contractor has been above average the qualifications of the personnel assigned to the task and the quality of workmanship performed was highly satisfactory. The company has in all cases been responsive to customers requests. The delay in final acceptance and failure to meet some of the design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	
five (5) copies of the Maintenance Manual for the P.I. Change Detector Prototype. These manuals constitute final delivery of all items specified in the contract. However, the attached copy of a letter in the PADE project file indicates that several deliverable items may still be held by the contractor. This should be determined during contract sottlement. Stated that "some of the breadboard components were sold to the AIF Force;" however, this action is not officially documented in the PADE project file. [AN ONLY OF THE PADE PROJECT FILE FILE CAST OF THE CAST OF THE Agency'S Contracts. This CRT had sustained damage and was not useable on the Change Detector. The overall performance of this contractor has been above average the qualifications of the personnel assigned to the task and the quality of workmanship performed was highly satisfactory. The company has in all cases been responsive to customers requests. The delay in final acceptance and failure to meet some of the design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	
indicates that several deliverable items may entract sottlement. Stated that "some of the breadboard components were sold to the Air Force;" however, this action is not officially documented in the FEDS project file. One Cathode Ray Tube type C5816 for use on another of this Agency's contracts. This CRT had sustained damage and was not useable on the Change Detector. The overall performance of this contractor has been above average the qualifications of the personnel assigned to the task and the quality of workmanship performed was highly satisfactory. The company has in all cases been responsive to customers requests. The delay in final acceptance and failure to meet some of the design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	r
in the PEDS project file. One Cathode Ray Tube type C5816 for use on another of this Agency's contracts. This CRT had sustained damage and was not useable on the Change Detector. The overall performance of this contractor has been above average the qualifications of the personnel assigned to the task and the quality of workmanship performed was highly satisfactory. The company has in all cases been responsive to customers requests. The delay in final acceptance and failure to meet some of the design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	
this Agency's contracts. This CAT had sustained damage and useable on the Change Detector. The overall performance of this contractor has been above average the qualifications of the personnel assigned to the task and the quality of workmanchip performed was highly satisfactory. The company has in all cases been responsive to customers requests. The delay in final acceptance and failure to meet some of the design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	
The qualifications of the personnel assigned to design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	
The delay in final acceptance and failure to meet some of the design objectives are attributed to official technical changes made in the contract and to the decision to deliver without a complete electronic checkout at the factory.	****
Development Branen, resus	
Development Branch, Paus	. s
Development Branch, Posts	
· · · · · · · · · · · · · · · · · · ·	

Approved For Release 2002/09/03 : CIA

TO ONCLASS IF IED

CIA RDP78B94747A992600010024-

SECRET

en e	Paris de la Company de la comp
	Approved For Release 2002/09/03 SECRET 8B04747A002600010024-7
90 (13	
	26 Movember 1966
25X1A	
25/ IA	
	Dear Sirs:
25X1A	It was agreed in discussion with on 6 November 1964
20,(1),	that we would furnish a listing of certain non-expendable from which
Charles I	were not delivered with the Change Detector.
	The following are identifications of the items discussed:
25X1A	Ball slide alum; 2 each
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Ball slide alun;
25X1A	Power supply, Motor, Induction, L each 4 each
25X1A	Motor, Induction, 4 each
25X1A	Power Supply Magneclutch, 4 each
计集	Telemicroscope 2 each
25X1A/	Motor 3 each
	Motor 2 each 3 each
	Lens entarging, Goers, 16.8,
	300mm 2 each
25X1A	These items are all subject to delivery against unless
, N	it is found more convenient by the Government to furnish UFE (Government Furnished Equipment) against enother contract.
25X1A	
25X1A	The enclosed Enlarger photographs are for
	Sincerely
2574	
25X1A\	Topiosure .
	Approved For Release 2002/09/03; CIA-RDP78B04747A002600010024-7