

ROUTING			
TO:	NAME AND ADDRESS	DATE	INITIALS
1			
2			
3			
4			
	ACTION	DIRECT REPLY	PREPARE REPLY
	APPROVAL	DISPATCH	RECOMMENDATION
	COMMENT	FILE	RETURN
	CONCURRENCE	INFORMATION	SIGNATURE
REMARKS:			
FROM: NAME, ADDRESS, AND PHONE NO.			DATE

**SECRET**

72

(Security Classification)

NOFORN



25X1

(See inside cover)

CONTROL NO. Z-15388/83

NPIC/PEG (10/83)

COPY \_\_\_\_\_ OF \_\_\_\_\_

  
**Warning Notice**  
 Intelligence Sources or Methods Involved  
**NATIONAL SECURITY INFORMATION**  
 Unauthorized Disclosure Subject to Criminal Sanctions  


214

**SECRET**

(Security Classification)

**Warning Notice**  
**Intelligence Sources or Methods Involved**  
**(WNINTEL) or (D)**

**NATIONAL SECURITY INFORMATION**  
**Unauthorized Disclosure Subject to Criminal Sanctions**

**DISSEMINATION CONTROL ABBREVIATIONS**

<b>NOFORN-</b>	<b>Not Releasable to Foreign Nationals</b>
<b>NOCONTRACT-</b>	<b>Not Releasable to Contractors or Contractor/Consultants</b>
<b>PROPIN-</b>	<b>Caution-Proprietary Information Involved</b>
<b>ORCON-</b>	<b>Dissemination and Extraction of Information Controlled by Originator</b>
<b>REL . . .</b>	<b>This Information has been Authorized for Release to . . .</b>

Declassified in Part - Sanitized Copy Approved for Release 2012/01/27 : CIA-RDP84T00171R000202140001-3

**Page Denied**

Declassified in Part - Sanitized Copy Approved for Release 2012/01/27 : CIA-RDP84T00171R000202140001-3

**SECRET**

25X1

**(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER**Page 1 of 1Attachment to Z-15388/83  
NPIC/PFG (10/83)

Copy \_\_\_\_\_

ARRIVAL OF SERVICE GANTRY COMPONENTS  
TYURATAM SPACE LAUNCH SITE A1, USSR

25X1

1. SIGNIFICANCE: SERVICE GANTRY REPLACEMENT COMPONENTS HAVE BEEN DELIVERED TO THIS DAMAGED AND INCOPERATIVE LAUNCH SITE SINCE \_\_\_\_\_ (SWN)

25X1

2. REMARKS: THREE STABILIZER ARMS AND SEVERAL UNIDENTIFIED ARCH-SHAPED PIECES OF EQUIPMENT ARE ON THE APRON. THE THREE STABILIZER ARMS PROBABLY WERE DELIVERED FROM TYURATAM SPACE LAUNCH SITE B1 \_\_\_\_\_ SERVICE GANTRY COMPONENTS ARE BEING STORED AT LAUNCH SITE B1 AWAITING REFURBISHMENT OF THAT LAUNCH SITE. A FOURTH STABILIZER ARM IS EXPECTED TO BE DELIVERED TO SITE A1. ONE PARTIALLY DISMANTLED SERVICE ARM, REMOVED FROM THE DAMAGED LAUNCH PAD \_\_\_\_\_ IS ALSO ON THE APRON WHILE A SECOND SERVICE ARM REMAINS IN PLACE ON THE LAUNCH PAD. THE RAPID PACE OF THE ONGOING REPAIR EFFORT INDICATES THE IMPORTANCE THE SOVIETS ARE PLACING ON THEIR ATTEMPT TO HAVE THIS SITE OPERATIONAL AS SOON AS POSSIBLE. (SWN)

25X1

25X1

3. \_\_\_\_\_ COORDINATES 45-55-12N 063-20-33E

25X1

25X1

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

25X1

**WARNING NOTICE**  
Intelligence Sources  
and Methods Involved

**SECRET**

25X1