SAIGON BASE MONTHLY REPORT JUNE 1970

- I. GENERAL
- 1. Total block time for June was was 5588 hours as compared with 5825 hours in May and 5811 hours in April 1970.
- 2. The security condition in Saigon remains "stable". There were several student demonstrations to establish peace in Vietnam plus several other obscure issues of government controls and school administration. They did not reach the violent proportions of those routinely experienced in the USA. The veterans manifested dissent by constructing market stalls on public property along several boulevards in downtown Saigon which degraded the environment and disrupted the orderly conduct of business and traffic in these areas. The veterans were complaining about the lack of veterans benefits. After several days of strong persuasion by the police, the veterans agreed to dismantle their stalls. At the moment, all is calm in Saigon.
- 3. Labor conditions: Because of the cutback in labor strength at Thu Duc due to the take-over by RVN from USAID of extensive warehousing facilities, there was a threat of a General Sympathy Strike with employees of Esso, Caltex, Shell and several lesser companies participating. The general strike, due to government controls and lower wages never "got off the ground". It is gratifying to note that AAM employees never considered the possibility of participation.
- 4. BM Saigon returned from 35 days annual leave in the Z.I. to find that SOM Parrish had done an excellent job of filling in as Acting BM during his absence. Meanwhile our management-level manning is sagging due to accrued leave which must be liquidated. Boyd Mesecher (MTS) is on four months leave (1 May through 31 August). SZ DAD Cambre is on four months leave (11 July through 17 October 1970). MF/RW Hitchman will be on leave 20 July through 30 Sept. PM, Frank Nihill is on leave 13 July through 8 August. ADSAFE George Keller will be on leave 20 July through 8 Sept. Al Harris (Assistant to SOM Parrish) is on leave 25 June through 30 July. Other absences on leave of lower levels of supervision result in very thin management manning in SVN, however, the "second team" seems to be carrying the load quite well.
- 5. Air Cambodia is operating in and out of Saigon carrying well-dressed "refugees" on a non-scheduled basis four to six days a week.

With the exception of a few intransit passengers to Singapore, the outbound passenger manifest is almost negative.

- 6. We have performed a number 2 service and major clean-up of VTB N3728G in anticipation of transfer to UTH. Meanwhile it is being kept in service under VN-70 Contract. After transfer, 28G will be replaced on VN-70 Contract by VTB N9838Z now in temporary storage.
- 7. It is apparent we are about to "overrun" AR #8320 for the Danang hostel by approximately US\$1700.00 due to the discontinuance of NSA supply support and per diem costs for TCS personnel from GND SGN to perform the work. This was an oversight on our part. In any event an existing AR #2255 to upgrade SZ DAD quarters, which will now become part of the hostel facilities, was with held from further work due change in programming and is more than adequate to provide funding for the total Danang hostel project which includes the existing hostel plus SZ quarters which are being converted to additional hostel facilities under the cited Appropriation Requests.
- 8. As of 8 July 1970, Continental Air Services has operated the following fleet in SVN:

C-47	8
DO-28	2
Skyvan	1
Beech Baron	6
H-18 Super Beech	1
Total	18

II. CUSTOMER RELATIONS

Have reached an all time high. There are no known areas of misunderstanding or question involving AAM Operations.

III. FACILITIES DEVELOPMENT

In the area of facilities development it appears there is very little left to be accomplished to achieve a completely efficient configuration:

- (1) AR 2438 Concrete Drainage Ditch and Concrete Pavement DAD. This project is 60% complete and progressing on schedule.
- (2) AR 2422 Renovation of Operations Building Saigon. Contract has been signed. Work should commence in late July.
- (3) AR 2449 Saigon Terminal Parking Apron. Out for bid. Expect to get this project moving soon.

(4) Project 6702 - 204B touchdown Pads SGN. Form F has been submitted for Customer consideration. We will continue to exert pressure on this project but at the moment it does not look very hopeful.

IV. GENERAL AFFAIRS (Unreported)

V. FISCAL
Saigon Base Accounting was moved into new offices located on the second floor of the RAD Maintenance building south side of Hangar #1.

The station allowance increase for American employees was reflected on the June payslips and was retroactive from April 1, 1970. The adjustment for personnel are being made now and will be reflected in next month's report.

The station allowance increase for American and TCN personnel has tended to tone down the hard feelings of ground personnel, but the general opinion is that ground personnel should receive other benefits the pilots received. Such other benefits being increased weight allowance for personnel effects, better insurance coverage and family relocation per diem.

VI. MEDICAL

Number of sick call: 1269

Accidents: 30

Hospitalized sick call: 1 died

Unhospitalized accident: 30 Hospitalized accident: None

Outcalls: 3

Physical examination: 34


Sick leaves: 211

Apart from routine activities, spent a week in Taiwan escorting three RVN Government Officials (from the Ministries of Labor and Education) on a tour of Company facilities. The Officials came away extremely impressed with the facilities and our training programs, and this public relations effort should aid us considerably in future dealings with the government (especially with respect to securing Work Permits for our TCNs).

Our Vietnamese employees declined to participate in either of the month's general strikes, the second of which ultimately involved over 100,000 workers. This non-participation is a fine tribute indeed to our management - employee relations at all levels.

The plastre is being traded on the open market at approximately VN\$ 370 to US\$1.

Personnel Strength - Saigon Base



HOSTEL OCCUPANCY

During the month of June, only three Certificates of "non-availability of company furnished accommodations" were issued.

VIII. TECHNICAL SERVICES

1. Overall activities in SVN Stations were lower than that of recent months. The reduced activity was a fairly direct reflection of the 4.7 percent drop in overall flying.

The rainy season has brought its usual problems of productive time losses, interruptions of communications and aircraft ignition systems breakdown. Power interruptions have been less than in previous years.

Preparations for the implementation of the new Skilled Labor Cost Accounting System required a lot of attention and training time by all employees; particularly Supervisory.

Facilities improvements at SGN included the completion of the Accounting offices and movement of the accounting personnel to the RMD Shops Building. The completion of a walkway from the hangar to the terminal has contributed the safety of personnel by reducing pedestrian traffic on the aircraft ramp. Concreting of the Danang terminal/hangar area is well underway. This project, as well as the Danang Hostel renovation has required considerable time and attention from GMD

- 2. Aircfaft Maintenance Fixed Wing
 As a result of a decrease in total number of aircraft departures and
 arrivals, the general activity declined. Routine maintenance
 comprised the major portion of the workload.
- 3. Rotary Wing June workload was average until the last week; one number two service was performed at VO3, eight at VO1, one number three A at VO1, two engine hot section inspections, and three engine changes.

Flying time for the month was down somewhat to about 980 as compared with the previous three month of 1050.

4. Shops - The overall workload for the early part of June was routine but turned heavy toward the last part due to a PC-6 and a helicopter No. 4 service.

The Shops Equipment Shop has placed increased effort in reworking and marking VTB seats on a fleet basis.

- 5. Planning S/PLNG has made a tour to VCA, DAD and NHA this month giving training classes to the Technical Services personnel. Training classes for RMD and RGMD personnel in SGN Base were held at the same time by S/TT, SGN
- 6. General Maintenance AR 2421, relocation of offices is well along. AR 2422, renovation of the Operations building, the contract was signed with A&M Enterprise. AP. 2438, Concrete Paving in DaNang was started this month. AR 8320, Renovation of the Hostel in DaNang begun on 24

June, this is being accomplished by in-house labor.

- 7. Building and Grounds Maintenance: The grass plots in front of the Cafeteria were reworked and seeded with grass seeds obtained from HongKong. However the seeds were received with zero germination.
- 8. Communications Maintenance We were more concerned during the month with the cables for teletypes and telephones which gave us more delays on traffic than the equipment to which they are connected.

Teletype circuits and Maintenance: Most of the troubles were due to bad cables. If there is a heavy down pour in one day, the following day TTY circuits are all in bad shape including telephone trunk lines. It takes two, three or four days before the circuits are restored to normal. The Creed TTY circuit on the sending side was out twelve days because of defective lines. Cable trouble is also true with CCR-CAT TTY circuits this time of the year.

Transmitters' Maintenance: We encountered trouble with our daytime 34-A HF transmitter. The 30-volt rectox rectifiers developed leakage which brought down the 30-volt control voltage to only 20 volts.

9. Technical Training - Courses completed: Supervisor management, 2048 maintenance. The SGN-line Service Mechanic course has been delayed due to the poor response of the Vietnamese to Air America's "Help wanted ads".

Shipping/Receiving activities experienced a slightly decrease.

Procurement section experienced a little smaller number of transactions than May. A total of 210 line items of commodities were purchased from the local market this month. Total value of commodities purchased from Saigon/Cholon market amounted to VN\$658,204.00.

Since the Naval Support Activity (NSA) in DAD has been deactivated on 14 June 70, Procurement switched its sources to HKG and local vendors for certain items. This entailed a somewhat slower procedure and more careful approach to bying. The sometimes wide range of qualities, prices and local problems have significantly added to the workload, when compared to the relatively simpler NSA operation. Negotiations to open an account with the U.S. Army Vietnam are still being carried on.

10. Customs. Surface vessel shipments are becoming more complicated as the customs requirements for documentation has been increased. On re-exportations, the temporary import documents must be furnished. This requirement can be easily filled on large equipment or vehicles.

X. OPERATIONS

- 1. Flight Time Report (See attachment A)
- 2. Ground Fire Incidents Report (See attachment B)
- 3. Accident reports

Date	A/C Type/No.	Location	Remarks
09	V TB/N6154U	V-11, SVN	During operation at V-11 number 3 blade sustained a nick approximately 1 inch deep, believed from a piece of small rock.
13	201B/N1304X	V-69,SVN	During post flight inspection noted a 1/2" hole in the leading edge of the tail rotor blade. The result of hostile action.

4. Flying Safety

No accidents or incidents since 2 January 1970.

5. Ground Transportation

Aggregate microbusses mileage	25071 km
Microbusses down-time	335 hrs 321
Microbusses passengers carried	3234 pax
Isuzu bus mileage	6009 km
Isuzu cus down time	55 hrs 541
Isuzu bus pax carried	10290 pax
Supply vehicle mileage	2946 km
Supply vehicle down-time	22 hrs 501

Flying

Cur time and most of our efforts were primarily concerned with DHCL/b851 and pilot requirements for same, Captains Broussard, Parker and McCauley and the over-temp of VTB N7770B.

Caribou B-851 arrived and was put to work by the customer shortly after it arrived. Because of the "B" registry there has been some difficulty in setting up proper crew manning in the program. The problem appears to be resolved on a temporary basis by cross training pilots. Presumably the Bid System will provide a final solution. Meanwhile the pilots in this program are "maxing" the time limit.

Investigation, coordination, termination and the hearings concerning Broussard and Parker definitely took a disproportionate amount of the month's time. The biggest single problem in this and similar cases is the involvement of FEPA and the AAM Agreement. Since FEPA benefits from the continuous services of a trained attorney, the odds are somewhat stacked in their favor when MFD is forced to present the prosecution side of a case without professional or trained legal help.

MFD visited Danang facilities. The most notable finding was the water which is taken from the well on the premises is grossly contaminated.

The Nhatrang quarters seem to be in good shape except the lack of air conditioners which are definite necessities for our crews to get adequate

rest while on HON. A steady stream of complaints has been produced by this one shortage.

Crews lockers are now available in Saigon and are being issued.

And another month accident free.

XI. TRAFFIC/AAM

	<u>May</u>	June
Passengers departure SGN (all contracts) Passengers arrival SGN (all contracts) Outbound cargo SGN Inbound cargo SGN	5,414 6,092 81,608 70,754	5,432 6,231 146,640 70,700

THAFFIC/USAID

Cargo (including AF Caribou A/C)

	May	June
Outbound (1bs) SGN Inbound (1bs) SGN	1,893,269 364,518	800,054 392,621

E.J. Theisen

SAIGON BASE FLIGHT TIME REPORT

- <u>JUNE 1970</u> -

I.	Contract 7001	**
----	---------------	----

Concreat /OUI -	Rev	entie	Non-Re	evenue
A/C No.	Block Time	Flight Time	Block Time	Flight Time
n67981.	156+08	134+37		
N67985	195+19	160+31	3+50	3+28
8928	71+38	56+45	1+52	1+36
B910	79+32	66+31	2+47	2+20
B912	120+49	102+33	3+34	2+48
6147	54+22	43+43	3+00	2+25
8084	58+55	47+07		•
5559	120+50	104+22		
5994	208+39	89+07	10+52	9+20
B629	83+25	67+66	20+16	18+48
N539X	159+42	139+16	4+25	3+40
N544Y	84+44	115+25	5+47	4+43
B851	44+22	36+28	3+52	2+56
N9518Z	129+27	110+06	1+40	0+52
n6154U	30+25	25+53	•	
199562	124+34	107+21		
М7770В	61+14	52+19	2+20	1+38
19577 Z	1+20	0149	11+46	9+19
136740	77+15	65+47	•	
¥91295	76+30	67+01		
13728G	103+19	89+51	1+20	1+05
37695 0	74+18	62+57		-
N180K	94+54	83+51		
N2851.	115+41	100+30		
1391R	56+09	49+47		
1394 E	87+42	73+53	2+52	1+36
Marth	119+07	105+18	0+55	0+32
nigei	98+36	89+29	2+30	1+48
N1531	121+23	110+10	5+33	4+21
10.2450	5+55	5+33		
k74en	46+41	43+08	1+33	1+05
N1521	102+08	85+00	9+49	8+52
Hibal	129+00	105+51	3+22	2+37
N185K	48+59	39+46	1+16	0+50
N192X	29+13	24+05		
W194X	108+48	93+02	4+45	3+33
k393r	40+33	36+17		
N1303X	99+47	99+47	3+20	3+20
11304I	154+32	154+32	3+30	3+30
N1305X	23+34	23+34	0+30	0+30
10306X	132+24	132+24	6+35	6135
101307 X	95+21	95+21	11+23	11+23

	н651ДР N8535Р	87+05 138+09	87+05 138+09	2+15 1+00	2+15 1+00
	Sub total	4012+12	3522+47	138+29	118445
2.	Contract 7002 -				
	и 544Y	10+25	8+20		
	B651	3+40	2+33		
	N9516Z	5+38	4+59		
	n61540	63+39	53+47		
	N9956 Z	5+42	4+52		
	¥77708	44+33	37+37		
	136740	44+53	39+20		
	N91295	16+58	14+34		
	13728G	3+29	3+03		
	¥7695 0	29+57	25+01		
	MISOK	24+24	21+20		
	N2851.	17+22	15445		
	N391R	25+19	22+02		
	1394R	29+56	26+32		
	жуцц	6+15	5+27		
	N198X	23+00	20+08		
	M2.53L	2+59	1+32		
	112450	61+30	53+54		
	N748 N	96+06	88+17		
	N152L	2+50	2+15		
	KISAL	46+05	37+01		
	KL85K	77+17	70+31		
	1192X	53+29	75+15		
	KISAI	2+52	2+39		
	N393R	62+45	57+21		
	N1303X	24+15	24+15		
	1030LX	12+38	12+38		
	N1305X	61+36	61+36		
	N1306X	3+45	3+45		
	M1307X	3+03	3+03		
	и8514.Р	28+03	28+03		
	N8535P	33+26	33+26		
	Sub total	926149	860+51		
3.	Contract 7003 -				
	B926	37+19	32+17		
	B910	49+54	42+41		
	6147	3+47	2+19		
	6084	2+54	2+17		
	N539Y	37+20	32+47		
	#544Y	14+44	11+39		
	8851	16107	12+52		
			400-1-200		

N95182 0-56 0-42 N6154U 1+47 1+11 N99562 1+32 1+24 N3674G 2+51 1+51 N3728G 1-65 0-40 N7695C 0+59 0-40 N180K 2+12 1-447 N2851 7-52 6-17 N391R 2+09 1+31 N994R 6+50 5-40 N994R 6+50 5-40 N994R 5-55 5-40 N1984 5-55 5-40 N1984 5-55 5-40 N1984 5-55 5-40 N1984 5-60 4-28 N1984 5-60 4-28 N1984 5-60 4-28 N1984 1-50 2-37 N1921 6-68 4-39 N1921 1-67 0-50 N1921 1-68 0-57 N1903X 13-21 13-21 N304X 1-28 0-57 N304X 1-28 1-68 N3150X 1-68 1-68 N3150X 1-68 1-68 N3150X 1-68 1-68 N3150X 1-68 1-68 N3121 0-68 5-430 Sub total 95-24 81-14 5. Contrast 0069 - N9664AC 97-36 83-08 N3121 0-68 5-430 Sub total 120-39 108-28 TOTAL EXTENSIVE BLOCK TIME 138-29						
N6154U 1-47 1-111 N99962 1-32 1-24 N99762 1-32 1-24 N3674G 2-51 1-51 N3728G 1-05 0-40 N7695C 0-59 0-40 N180K 2-12 1-47 N285L 7-52 6-17 N285L 7-52 6-17 N391R 2-09 1-31 N94R 6-50 5-01 N94A4 5-55 5-08 N198Z 5-04 4-28 N198Z 5-04 4-28 N198Z 1-701 6-16 N748N 2-150 2-37 N152L 6-08 4-39 N182L 3-19 2-18 N185K 10-01 6-39 N192X 1-28 0-57 N1303X 13-21 13-21 N1307X 10-18 10-18 N851AF 29-12 29-12 N8535F 52-51 52-51 Sub total 286-04 244-39 4. Contrast COSQ - N9664C 97-36 83-08 N31295 5-26 4-32 N152L 6-08 5-30 Sub total 1-52 1-43 N152L 8-39 7-52 N185L 3-51 3-15 Sub total 120-39 103-28 TOTAL REVENUE BLOCK TIME 5482-99 TOTAL NCM-REVENUE BLOCK TIME 138-29			N95282	0+56	0+42	
N99562 1-92 1+24 N367MG 2+51 1+51 N3728G 1+05 0+40 N4695C 0+59 0+40 N180K 2+12 1+47 N285L 7+52 6+17 N391R 2+09 1+31 N394R 6+50 5+01 N94M 5+55 5+08 N198K 5+04 4+28 N193L 7+01 6+16 N748R 2+50 2+37 N352L 6+08 4+39 N182L 3+19 2+18 N185K 10+01 6+39 N192Z 1+09 0+50 N192Z 1+09 0+50 N194Z 1+28 0+57 N130AL 13+21 13+21 N30AL 13+21 13+25 N30AL 1			N6154U	1+47	1+11	
#367McC 2+51 1+51 #3728G 1+05 0+40 #1695C 0+59 0+40 #180K 2+12 1+47 #285L 7+52 6+17 #391K 2+09 1+31 #394K 6+50 5+01 #394K 6+50 5+01 #394K 5+55 5+08 #194X 5+04 4+28 #153L 7+01 6+16 #748# 2+50 2+37 #152L 6+08 4+39 #184L 3+19 2+18 #185K 10+01 6+39 #194X 1+28 0+57 #1303X 1+28 0+57 #1303X 13+21 13+21 #1307X 10+18 10+18 #8514F 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract COSO - #95777Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 75+24 81+14 5. Contract COSO - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #168L 3+51 3+15 Sub total 120+39 103+28 TOTAL EXTENSE BLOCK TIME 54,4108 #812+59 TOTAL HUS-KEVENUE BLOCK TIME 138+29						
N3728C				-	₹	
N7695C 0+59 0+40 N186K 2+12 1+47 N285L 7+52 6+17 N391E 2+09 1+31 N394R 6+50 5+01 N9444 5+55 5+08 N198K 5+04 4+28 N151L 7+01 6+16 N7488 2+50 2+37 N152L 6+08 4+39 N184L 3+19 2+18 N195K 10+01 6+39 N194X 1+28 0+57 N194X 1+28 0+57 N1303X 10+18 10+18 N300X 10+18 10+18 N870X 10+18 10+18 N870X 10+18 10+18 N870X 2+12 29+12 N8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract COSO - N9577Z 88+24 75+11 N192X 0+52 0+33 N1521 6+08 5+30 Sub total 95+24 61+14 5. Contract COSO - N9664C 97+36 83+08 N91295 5+26 4+32 N1521 8+39 7+52 N184L 3+51 3+15 Sub total 120+39 103+28 TOTAL EXVENUE BLOCK TIME 544,108 TOTAL EXVENUE BLOCK TIME 544,108 TOTAL NEWENUE BLOCK TIME 138+29				•	•	
N180K 2+12 1+47 N2851 7+52 6+17 N391R 2+09 1+31 N394R 6+50 5+01 N5444 5+55 5+08 N194X 5+55 5+08 N194X 5+55 5+08 N194X 5+50 2+37 N1531 7+01 6+16 N746N 2+50 2+37 N1521 6+08 4+39 N1841 3+19 2+18 N185K 10+01 6+39 N194X 1+28 0+57 N196X 1+28 0+57 N196X 1+28 0+57 N196X 1+28 0+57 N196X 10+18 10+18 N8514F 29+12 29+12 N8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract CO30 - N9577Z 88+24 75+11 N192X 0+52 0+33 N152I 6+08 5+30 Sub total 95+24 81+14 5. Contract CO30 - N966AC 97+36 83+08 N91295 5+26 4+32 N152I 8+39 7+52 N185K 3+15 2+58 N184I 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441-08 TOTAL REVENUE BLOCK TIME 5441-08 TOTAL NON-REVENUE BLOCK TIME 138+29				_		
#2851 7+52 6+17 #391R 2+09 1+31 #394R 6+50 5+01 #394R 6+50 5+01 #394R 6+50 5+01 #394R 5+64 4+28 #1531 7+01 6+16 #748R 2+50 2+37 #1521 6+08 4+39 #1841 3+19 2+18 #185K 10+01 6+39 #185X 10+01 6+39 #195X 1+69 0+50 #195X 1+28 0+57 #130AI 13+21 13+21 #130AI 13+21 13+21 #130AI 13+21 10+18 10+18 #851AF 29+12 29+12 #8535F 52+51 52+51 \$wb total 286+04 244+39 4. Contract CO30 - #9577Z 88+24 75+11 #152X 0+52 0+33 #1521 6+08 5+30 Sub total 95+24 81+14 5. Contract CO59 - #9664C 97+36 83+08 #91295 5+26 4+32 #615AU 1+52 1+43 #152I 8+39 7+52 #185K 3+15 2+58 #1841 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441-08 #812+59 TOTAL REVENUE BLOCK TIME 138429				• •		
#391R 2+09 1+31 #394R 6+50 5+01 #9444 5+55 5+08 #196X 5+04 4+28 #1531 7+01 6+16 #748H 2+50 2+37 #1521 6+08 4+39 #1841 3+19 2+18 #185K 10+01 6+39 #194X 1+28 0+57 #194X 1+28 0+57 #196X 1+09 0+50 #194X 1+28 0+57 #196X 10+18 10+18 #851AF 29+12 29+12 #8535F 2+51 52+51 Sub total 286+04 244+39 4. Contract 0030 - #9577Z 88+24 75+11 #192X 0+52 0+33 #1521 6+08 5+30 Sub total 95+24 81+14 5. Contract 0069 - #966AC 97+36 83+08 #91295 5+26 4+32 #615AU 1+52 1+43 #1521 8+39 7+52 #165K 3+15 2+58 #1841 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 54A1+08 #812+59 TOTAL REVENUE BLOCK TIME 138+29						
#394R 6+50 5+01 #9444 5+55 5+08 #1948 5+04 4+28 #1531 7+01 6+16 #1488 2+50 2+37 #1521 6+08 4+39 #1841 3+19 2+18 #185K 10+01 6+39 #192X 1+09 0+50 #192X 1+09 0+50 #193X 1+28 0+57 #1303X #1304X 13+21 13+21 #1307X 10+18 10+18 #8514F 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contrast 0050 - #9577Z 88+24 75+11 #192X 0+52 0+33 #1521 6+08 5+30 Sub total 95+24 81+14 5. Contrast 0069 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #1521 8+39 7+52 #165K 3+15 2+58 #168K 3+15 2+58 #168K 3+15 2+58 #168K 3+15 3+15 Sub total 120+39 108+28 TOTAL REVENUE BLOCK TIME 5441-08 #107AL REVENUE BLOCK TIME 138+29					7	
N9444					_	
#198X 5+04 4+28 #1531 7401 6+16 #748# 2+50 2+37 #1521 6+08 4+39 #1841 3+19 2+18 #185K 10+01 6+39 #192X 1+69 0+50 #194X 1+28 0+57 #1303X #1304X 13+21 13+21 #1304X 10+18 10+18 #8514F 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract COSO - #9577Z 88+24 75+11 #192X 0+52 0+33 #1521 6+08 5+30 Sub total 95+24 81+14 5. Contract COSO - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #1521 8+39 7+52 #185K 3+15 2+58 #1841 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 #812+99 TOTAL NOW-REVENUE BLOCK TIME 138+29				_	-	
#1531 7+01 6+16 #748H 2+50 2+37 #1521 6+08 4+39 #1841 3+19 2+18 #185K 10+01 6+39 #192X 1+09 0+50 #130X 1+28 0+57 #130X 13+21 13+21 #130X 10+18 10+18 #851AF 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contrast CO30 - #9577Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contrast CO30 - #966AC 97+36 83+08 #91295 5+26 4+32 #615AU 1+52 1+43 #152L 8+39 7+52 #185K 3+15 2+58 #186L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 #812+59 TOTAL REVENUE BLOCK TIME 138+29					•	
## 2 + 50						
#1521 6+08 4+39 #1841 3+19 2+18 #185K 10+01 6+39 #192X 1+69 0+50 #194X 1+28 0+57 #1303X #1304X 13+21 13+21 #1307X 10+18 10+18 #8514F 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contrast CO30 #9577Z 88+24 75+11 #192X 0+52 0+33 #1521 6+08 5+30 Sub total 95+24 81+14 5. Contrast CO69 #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #1521 8+39 7+52 #185K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 #812+59 TOTAL NCM-REVENUE BLOCK TIME 4812+59				7+01		
#1841 3+19 2+18 #185K 10+01 6+39 #192X 1+09 0+50 #194X 1+28 0+57 #1303X #1304X 13+21 13+21 #1307X 10+18 10+18 #851AF 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract CO30 - #9577Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract CO69 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154W 1+52 1+43 #152L 8+39 7+52 #185K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME \$4812+99 TOTAL REVENUE BLOCK TIME 138+29			H7L8H	2+50	2+37	
#185K 10+01 6+39 #192X 1+69 0+50 #194X 1+28 0+57 #1303X #1304X 13+21 13+21 #1307X 10+18 10+18 #8514F 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract CO30 - #9577Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract CO69 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #6154U 1+52 1+43 #152L 8+39 7+52 #165K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 #107AL REVENUE BLOCK TIME 4812+99 TOTAL NON-REVENUE BLOCK TIME 138+29			1152L	6+08	4+39	
#192X 1+09 0+50 #194X 1+28 0+57 #1303X #1304X 13+21 13+21 #1307X 10+18 10+18 #8514P 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract COSO - #9577Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract COSO - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #6154U 1+52 1+43 #152L 8+39 7+52 #165K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 54812+99 TOTAL NON-REVENUE BLOCK TIME 4812+99			N184L	3+19	2+18	
#192X 1+09 0+50 #194X 1+28 0+57 #1303X #1304X 13+21 13+21 #1307X 10+18 10+18 #8514P 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract COSO - #9577Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract COSO - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #6154U 1+52 1+43 #152L 8+39 7+52 #165K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 54812+99 TOTAL NON-REVENUE BLOCK TIME 4812+99			N185K	10+01	6+39	
#194X 1+28 0+57 #1303X #1303X 13+21 13+21 #1307X 10+18 10+18 #851AF 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract 0030 - #95777Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract 0069 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #165K 3+15 2+58 #168L 3+51 3+15 Sub total 120+39 108+28 TOTAL REVENUE BLOCK TIME 5441+08 #107AL REVENUE BLOCK TIME 5441+08 #107AL NCM-REVENUE BLOCK TIME 138+29			11192X	1+09		
#1303X #1304I 13+21 13+21 #1307Z 10+18 10+18 #8514F 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contrast 0030 - #9577Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contrast 0069 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #165K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 108+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 4812+79 TOTAL NCM-REVENUE BLOCK TIME 138+29			-	1+28	0+57	
M130LI 13+21 13+21 M1307X 10+18 10+18 M851AF 29+12 29+12 M8535F 52+51 52+51 Sub total 286+0L 2LL+39 4. Contract COSO - M9577Z 88+2L 75+11 M192X 0+52 0+33 M152L 6+08 5+30 Sub total 95+2L 81+1L 5. Contract CO69 - M966LC 97+36 83+08 M91295 5+26 L+32 M152L 8+39 7+52 M165L 1+52 1+L3 M152L 8+39 7+52 M165K 3+15 2+58 M165K 3+15 2+58 M168L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5LL+08 TOTAL REVENUE BLOCK TIME L38+29					• • •	
#1307X 10+18 10+18 #8514F 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract CO30 #9577Z 88+24 75+11 #192X 0+52 0+33 #1321 6+08 5+30 Sub total 95+24 81+14 5. Contract CO69 #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #1521 8+39 7+52 #1655K 3+15 2+58 #1841 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 4812+99 TOTAL NOW-REVENUE BLOCK TIME 138+29				13+21	13+21	
#851AF 29+12 29+12 #8535F 52+51 52+51 Sub total 286+04 244+39 4. Contract CO30 - #95777Z 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract CO69 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #6154U 1+52 1+43 #152L 8+39 7+52 #185K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 #107AL REVENUE BLOCK TIME 138+29			- ,			
Sub total 286+04 244+39 4. Contract COSO - #95777 88+24 75+11 #192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract COSO - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #1685K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 54812+59 TOTAL NOW-REVENUE BLOCK TIME 138+29						
Sub total 286+04 244+39 4. Contrast CO30 N95777 88+24 75+11 N192X 0+52 0+33 N152L 6+08 5+30 Sub total 95+24 81+14 5. Contrast CO69 N9664C 97+36 83+08 N91295 5+26 4+32 N6154U 1+52 1+43 N152L 8+39 7+52 N152L 8+39 7+52 N185K 3+15 2+58 N184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 4812+59 TOTAL NCM-REVENUE BLOCK TIME 138+29				-	· · · · · · · · · · · · · · · · · · ·	
4. Contrast CO30 - #9577Z			********	~	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
#95777			Sub total	286+04	244+39	
#192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract 0069 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #185K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29	4.	Contract COS	<u>o</u>			
#192X 0+52 0+33 #152L 6+08 5+30 Sub total 95+24 81+14 5. Contract 0069 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #152L 8+39 7+52 #185K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29			1195777	88421	75+11	
#1521 6+08 5+30 Sub total 95+24 81+14 5. Contract 0069 - #9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #1521 8+39 7+52 #185K 3+15 2+58 #1841 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441-08 TOTAL REVENUE BLOCK TIME 4812+59 TOTAL NOW-REVENUE BLOCK TIME 138+29				· ·		
5. Contract 0069 - N9664C 97+36 83+08 H91295 5+26 4+32 H6154U 1+52 1+43 H152L 8+39 7+52 M185K 3+15 2+58 M184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 54812+59 TOTAL NEW-REVENUE BLOCK TIME 138+29						
5. Contract 0069 - N9664C 97+36 83+08 H91295 5+26 4+32 R6154U 1+52 1+43 N152L 8+39 7+52 N185K 3+15 2+58 N184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 54412+59 TOTAL NCM-REVENUE BLOCK TIME 138+29			najes.	0100	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
#9664C 97+36 83+08 #91295 5+26 4+32 #6154U 1+52 1+43 #1521 8+39 7+52 #185K 3+15 2+58 #1841 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE FLICHT TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29			Sub total	95+24	81+14	
H91295 5+26 4+32 H615LU 1+52 1+43 H152L 8+39 7+52 H185K 3+15 2+58 H184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLCCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29	5.	Contract 006	2 -			
H91295 5+26 4+32 H615LU 1+52 1+43 H152L 8+39 7+52 H185K 3+15 2+58 H184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLCCK TIME 5441+08 TOTAL REVENUE BLOCK TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29			11966&C	97+36	83+08	
#6154U 1+52 1+43 #152L 8+39 7+52 #185K 3+15 2+58 #184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE FLICHT TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29			H91295			
N152L 8+39 7+52 N185K 3+15 2+58 N184L 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE FLICHT TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29						
NISSK 3+15 2+58 NISKL 3+51 3+15 Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE FLIGHT TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29						
Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE FLIGHT TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29						
Sub total 120+39 103+28 TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE FLIGHT TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29				•	-	
TOTAL REVENUE BLOCK TIME 5441+08 TOTAL REVENUE FLIGHT TIME 4812+59 TOTAL NON-REVENUE BLOCK TIME 138+29			SCHOOL ST		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	
TOTAL NON-REVENUE BLOCK TIME 138+29			Sub total	120+39	103+28	
			TOTAL NON-	HAENUE BIOC	k tine	

GRAND TOTAL BLOCK TIME

5579 + 37

GRAND TOTAL FLIGHT TIME

4931 + 44

FLIGHT TIME BY TIPE OF AIRCRAFT

	Re	Verities.	Hon-Rev	907/10
Type of A/C	Block Tim	e Flight line	Block Time	Plight Time
C-46	710+39	595+5 5	12+03	10+12
Bailed C-47	349+27	288+55	13+52	11+45
C-47	83+25	67+46	26+16	16+46
DHC-4	431+08	359+20	14+04	11+19
AIB	1095+39	936+19	17+06	12+54
Porter	1820+15	1614+11	32+35	25+14
204-B	950+29	950+29	28+33	28+33
TOTAL	5441+09	4812+59	138+29	118+45

L. G. Parrish SCM/SGN

ec: EM/SGN MFD/SGN TM/SGN File. I LIGHT ON ENTER

- SAIGON -

MONTHLY ACTIVITY REPORT 01-30 JUNE 1970

- Ground Fire Incidents -

Date :	A/C No., Type & Contract	Place	Description
02 Jun:	B912 C-46 7001	•	Capt. STALIMAN was on final at Tan-Son-Nhut when the heard one round pass near the starboard side of the a/c. Both pilot and co-pilot believed the a/c had sustained a hit, but no trace of the round or hole could be located. PIC continued his approach and landed safely. No personnel injury or a/c damage involved.
12 Jun:	B829 C-47 7001	: : XS 3727 : : :	A/c was at 1000 ft altitude (just below overcast) when pilot heard one round of groundfire. Pilot immediately ascended into overcast and shortly thereafter another shot was heard. No personnel injury or a/c damage involved.
12 Jun	n1303X 204,—B 7001	: ZC 1551 : t	: While a/c was loading paxs at chopper pad, one : round of 82mm mortar fire impacted approximately : 30 yards from a/c. A/c immediately took off and : returned to V206. No personnel injury or a/c : damage involved.
13 Jun	N91295 VTB 7002	: AQ 868020	: Capt. SHINE was on the approach to Ban-Me-Thuot : East when one small caliber round of groundfire : hit the right tire of the a/c. The tire did : not deflate and Capt. SHINE landed safely. A/c : returned to Nha-Trang where the tire was replaced

//- ART II

- Country Situation -

Air America's activity reports for South Vietnam are indicative of the low level of activity reported throughout the country this month. Danang, Bien Hoa, and Binh Thuy airfields received light indirect fire attacks sustaining minor damage. Saigon's activity was confined to two reported terrorists incidents and a continuation of student demonstrations. Allied operations in Cambodia diverted VC/NVA attention towards reestablishment of a seriously impaired logistic network outside of RVN. ARVN may soon have the opportunity to demonstrate the valuable experience and confidence gained in Cambodia in meeting an enemy "High Point" expected here earlier but delayed by Allied successes in Cambodia.

Reported by: R.N. Begien III OPSP/SGN

Saigon 10th July 1970

ቚጜፙጜዾ፞ጜጜጜጜጜጜጜጜጜጜጜጜጜ