	M. C. W.		CLASSIFIEL	MESSAGE	A The second sec	POST SEC	
ate	'. 0110Z 25 JAN	53	<u>S.F.</u>	C P ET	3 C/DA	7 6	To a section of
O :	DIRECTOR		EO 1	2958 3.3(b)(1)		19C	
ands áns.	05A (1-2-5-4	-5-6-7-8-9	-10)		PRIORITY		
NFO s	S/C (11)			~ 50		A CONTRACTOR OF THE CONTRACTOR	THE PROPERTY AND ADDRESS OF THE PARTY AND ADDR
	TOR: 0128Z	25 JAN 63		(6)		IN 63740	A CONTRACTOR OF THE PROPERTY O
TO	PRITY	5.5	N.C		CITE	7895	Control (Control)
	OXCART						

NO NIGHT ACTION

- 1. REFERENCE IS MADE TO THE ELECTRICAL PROBLEMS PLAGUING ACFT 123 AND CAUSING ABORT OF SEVERAL INS XLIGHTS. THIS WAS ERRONEOUSLY REPORTED AS INVERTER PROBLEMS WHILE IT TURNS OUT TO BE TROUBLE WITH THE SUNSTRAND CONSTANT SPEED DRIVE UNITS WHICH WERE ADAPTED TO THE J-75 ENGINES.
- 2. THESE DRIVES ARE NOT HOLDING CONSTANT SPEED AND FREQUENCY IS VARYING BETWEEN 175 CYCLES AND 500 CYCLES WHILE A CONSTANT 400 CYCLES IS REQUIRED. LAC DOES NOT HAVE A HANDLE ON THE PROBLEM YET BUT HAVE REPLACED BOTH CSD°S AND HAVE SENT TWO TROUBLEMAKERS TO BURBANK FOR INSPECTION AND TEST. FIRST CHECK OF THE NEW ONES IN THE ACFT WILL BE TONIGHT 24 JAN 63.

END OF MESSAGE

APPROVED FOR RELEASE DATE: AUG 2007

