

OK WASHITA 042340  
.TNNXTFA 042340

(RELAYED BY TNN)

OK TNNXTFA  
LAXXTFA 042355

TO VPC TNN

INFO VPA DS AVP TSR TNN MAAL HKG SVP-PCA EA/CEO WAS

MB & C HKG VP/T WAS CH/DISB HKG

SUBJECT ~~PROCUREMENT SERVICES FOR AAM~~

REFERENCE COTNN 75-197 DATED E28

VP/T WAS F75 042045Z

MAAL HKG F75 040745Z

MB&C HKG E75 140235Z

MAPDLAX E75 142242Z

REC-111  
AAM-354  
Wice  
10

- (A) BS75D011 ONE TWO HAVE RETURNED TO BELL FOR CREDIT SUBJECT TO TEN PERCENT RE-STOCKING CHARGE
- B) BS75C049 ONE SGN750269 ONE BS75C021 ONE BS75C043 ONE MATERIAL STILL ON HOLD NORTH HOLLYWOOD PER SRQ TNN E75 160440 PARA C CAN RETURN TO VENDORS FOR CREDIT HOWEVER THERE WILL BE NO INVOICES TO APPLY CREDITS TO. SUGGEST HOLD MATERIAL AND SHIP TO NEW MEXICO PENDING YOUR APPROVAL AND INSTRUCTIONS
- C) BS75D016 ONE PR STILL OPEN FOR DOLLARS 178 NO CENTS DELIVERY SCHEDULE F27 ADVISE IF STILL REQUIRED AND SHOULD PAYMENT BE MADE FROM AAM FUND
- D) BS75F001 ONE PR RECEIVED F02 DELIVERY SCHEDULE F13 ADVISE IF PAYMENT SHOULD BE MADE FROM AAM FUND
- E) BS75A026 ONE JOURDAN OUTER WING PANEL REINFORCEMENT KITS. THIS PR IS STILL OPEN AND BALANCE OF PAYMENT STILL OPEN IS DOLLARS 7425 NO CENTS DELIVERY SCHEDULE IS STILL UNKNOWN AS STILL UNABLE TO CONTACT JOURDAN
- F) HAS DISBURSEMENT CHECK ACTUALLY BEEN DEPOSITED TO CMB OR ENROUTE TO LAX
- G) BS75D001 ONE QTY OF 20 EACH NO CHARGE SAMPLING KITS ARE STILL ON HAND NORTH HOLLYWOOD PENDING SHIPPING INSTRUCTIONS
- H) ?74G039 ONE REPLACEMENT ON ORDER  
MAP

CORRECTION ON (#) H PARA ABOVE U S NUMBER SHOULD READ AS74G039  
REPEAT AS74G039  
MAPDLAX F75 042355Z  
~~WHIN 010~~

APPROVED FOR RELEASE  
 DATE: 20-Oct-2009

AF 002