

25X1A9a

CLASSIFIED MESSAGE

e-2000/09/11 : CIA-RDP71B00263R000200130001-3

ORIG: [REDACTED]
UNIT: C/MD/M/OSA
EXT: 7509
DATE: 21 SEPTEMBER 1967

S E C R E T

ROUTING		
D/M/OSA	10	
D/O/OSA	11	
D/SA	12	
IDEA/O/OSA	13	
RE/OSA	14	
	15	
	16	
DEFERRED	PRIORITY	URGENT
ROUTINE	OPERATIONAL IMMEDIATE	URGENT

TO :
FROM:
CONF:
INFO :

OSA 15 [initials] 42593

TO 25X1A6c **S E C R E T** INFO SEP 21 11 40 Z CITE [REDACTED] 9940

25X1A6c IMMEDIATE [REDACTED] INFO [REDACTED]

IDEALIST

25X1A6a 1. INFO RECEIVED FROM SAC [REDACTED] INDICATES INSPECTION OF AIRCRAFT

25X1A2g [REDACTED] REVEALS BOTTOM OF RIGHT WING HAS CRACK FROM 65 PERCENT CHORD FORWARD ELEVEN AND HALF INCHES. CRACK IS FOUR AND HALF INCHES OUT FROM WING ROOT. NO OTHER INFO AVAILABLE AT THIS TIME.

25X1A2g 2. [REDACTED] INDICATES AN X-RAY OF THE WINGS IS REQUIRED TO INSURE AIR WORTHINESS OF OUR AIRCRAFT.

25X1A2g 3. FOR [REDACTED] AVAILABLE INFO INDICATES [REDACTED] CAN ACCOMPLISH X-RAY INSPECTION MOST EXPEDITIOUSLY AT PLANT. REQUEST

25X1A2g [REDACTED] COORDINATE DIRECTLY TO ACCOMPLISH INSPECTION SOONEST.

25X1A2g 4. FOR [REDACTED] PLAN TO SHIP X-RAY EQUIPMENT AND OPERATORS TO YOUR STATION TO ACCOMPLISH INSPECTION ON AIRCRAFT 383 AS SOON AS POSSIBLE. WILL ADVISE DETAILS WHEN AVAILABLE.

25X1A9a

END OF MESSAGE

[REDACTED]

ORD: IDEA/O/OSA [signature]

COORDINATING OFFICERS

AD/M/OSA
RELEASING OFFICER

S E C R E T

GROUP 1
Excluded from automatic
downgrading and
declassification

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.