## CONFIDENTIAL

CLA	MAGERY ANALYSIS DIVISION	
Qui Vinh RR Br. Bridge No. 1 on NE 48-3.	North Vietnam	19 15N - 105 41E WG 720 302
REFERENCES PHOTO AMS L509 NE	8-3 25X1D	65044

LOCATION:

0.6 NM W. of Qui Vinh on the Hanoi-Vinh R.R.

DESCRIPTION:

WIDTH Single track
TYPE Through truss

MATERIAL Steel-Concrete
NO. OF SPANS 2
LENGTH OF EACH SPAN 130\*

STATUS:

One span completely destroyed, and one abutment completely destroyed. Bridge impassable.

COMPENSATIVE ACTION:

A light bridge is probably complete 100 yards south of the Qui Vinh Bridge.

Type and No. of spans of new bridge undetermined because of poor quality photography.



Declass Review by NIMA/DOD