

**ROUTING AND TRANSMITTAL SLIP** Date

TO: (Name, office symbol, room number, building, Agency/Post)	Initials	Date
1. EO/DDA	<i>[Signature]</i>	27 MAY 1983
2. ADDA	<i>[Signature]</i>	1 MAY 1983
3. DDA	<i>[Signature]</i>	31 MAY 1983
4. DD/A REGISTRY		
5. FILE: 106-7		

Action	File	Note and Return
Approval	For Clearance	Per Conversation
As Requested	For Correction	Prepare Reply
Circulate	<input checked="" type="checkbox"/> For Your Information	See Me
Comment	Investigate	Signature
Coordination	Justify	

**REMARKS**

5 Outages may be a little high but a number will be necessary to bring in new North Side Utility lines and interconnect within building



DO NOT use this form as a RECORD of approvals, clearances, and similar actions

FROM: (Name, org. symbol, Agency/Post)	Room No.—Bldg.
D/DDP/DDA 2-D-08 HQS	Phone No.

5041-102

OPTIONAL FORM 41 (Rev. 7-76)  
Prescribed by GSA  
FPMR (41 CFR) 101-11.206

STAT

STAT

ODP 83-0732  
SAF-E153-83

27 MAY 1983

DD/A Registry  
83-0341/14

MEMORANDUM FOR: Director of Logistics

FROM:   
Director of Data Processing

STAT

SUBJECT: Chilled Water Outage/Support to the SAFE  
Computer Center

1. The Director of the Consolidated SAFE Project Office has expressed concern regarding the potentially serious impact on the services provided by Project SAFE as a result of planned chilled water outages. It is our understanding that five outages in the next 12 months are currently planned by Headquarters Engineering Branch, each a minimum of 45 hours. During these times, services from the SAFE Center will not be available. In addition to the outage time required by the Office of Logistics, an additional 8-10 hours will be required by Office of Data Processing personnel after each outage to make the SAFE systems fully operational.

2. While the Northside Computer Center does not yet support the same number of users as the Ruffing Computer Center, it is an operational center supporting the DDI. We also have a commitment to provide reliable and timely service to the DIA until it moves to its new building in April-May 1984. Consequently, some means must be found to minimize, if not eliminate the impact upon critical SAFE services to the DDI and DIA.

3.  Chief, Configuration & Environmental Management Branch, ED, will be the point of contact to provide any assistance required of ODP to support this planning. He can be reached on extension

STAT

STAT

STAT

cc: DDA

ODP/CSPO: [redacted] (24 May 1983)

Retyped: D/ [redacted] EXO/ODP: [redacted] (26 May 1983)

STAT  
STAT

Dist:

Orig - Addressee

- 1 - DDA
- ( 2 - D/ODP/Chrono & ~~Subj: O&M/DDA/OL~~
- 1 - ODP/CSPO:SAFE/Chrono
- 1 - ODP/CSPO:SAFE Read File
- 2 - ODP/Registry