

20 SEP 62 18 39 Z
TOP SECRET

24 SEPTEMBER 1962

EDD N
WER [initials]
KB [initials]
RLP [initials]
RDO [initials]
PAG _____
SAH _____

25X1A

X

[REDACTED]

[REDACTED]

25X1A

OPCEN

25X1A HANDLE VIA COMINT CHANNELS ONLY

TO: [REDACTED]

CITE: OPCEN

25X1A ATTN: MR. [REDACTED]

6951

RE MISSION 3088, FIELD REPORTS FLIGHT CHECK OF SYSTEM III INDICATES NORMAL RESET PULSES ON TRACKS ONE AND TWO. REQUEST NSA MAKE SPOT CHECK AT BEGINNING, MIDDLE AND END OF TAPE ON OSCILLOSCOPE TO VERIFY LACK OF RESET PULSES. THIS MIGHT NARROW TROUBLE AREA TO POSSIBLE IN-FLIGHT MALFUNCTION AND AID IN TROUBLE-SHOOTING OPERATIONS.

END OF MESSAGE

25X1A

HANDLE VIA COMINT CHANNELS ONLY

Excluded from automatic
downgrading and
declassification

[REDACTED]