Declassified in Part - Sanitized Copy Approved for Release 2012/03/23 : CIA-RDP91-00058R000100070006-7

• •

R+63

<del>SECRET</del>



 Declassified in Part - Sanitized Copy Approved for Release 2012/03/23 : CIA-RDP91-00058R000100070006-7



OUTING AND TRANSMITTAL SLIP				1.
	KANSMILLAL SCIP	1	7 km	la la
A (Name, office symbol, ro building, Agency/Post) 1. A/DDA	om number,			JUL 19
2. DDA	· 17 JU	JL 198	N	
3. DAMS		1	8	JUL 19
· A	1-2 wet			
ARTS I	1 0		-	
Action	File	Note and Return		
Approval	For Clearance	Per Conversation		
As Requested	For Correction	Prepare Reply		
Circulate	For Your Information	See Me		
Comment	Investigate Signature			
Coordination	Justify			
REMARKS				

1-2: I think you toth will agive that there are mensary items which mut he finded. Poppen them now for your possible use in the your possible use in the forthering Compretties mity. DO NOT use this form as a RECORD clearances, and FROM: (Name, org. symbol, Agency/Post) Phone No. 5041-102 OPTIONAL FORM 41 (Rev. 7-78) A U.S. GPO: 1986-491-247/40012

Prescribed by 88A FPMR (41 CFR) 101-11,208

Declassified in Part - Sanitized Copy Approved for Release 2012/03/23 : CIA-RDP91-00058R000100070006-7

Mall Sa . . .

Sec. 1

STAT

Declassified in Part - Sanitized Copy Approved for Release 2012/03/23 : CIA-RDP91-00058R000100070006-7

17 JUL 1987.

MEMORANDUM FOR: Deputy Director for Administration

FROM: John M. Ray Director of Logistics

SUBJECT: Unfunded Request - Scattergood-Thorne

1. The Scattergood-Thorne property, 37 acres adjacent to the existing Headquarters Compound, has been added to the Agency's property holding. In order to provide a secure perimeter to the existing facility, a new fence must be installed around the property. An estimate of \$90,000 is required to satisfy this request.

2. Upon close inspection of the grounds, it is immediately apparent that little or no maintenance work has been performed in recent years. Fields must be trimmed back (and continually mowed, from here on out), tree branches should be pruned, and a significant amount of shrubbery needs care. Aside from the general ground work, a significant amount of debris has been left which must be removed. An estimate of \$40,000 is required to clean up and maintain this property.

3. The building structures (seven on the property) have similarly received little or no maintenance. In order to protect the interior of the facilities, work should commence immediately on roofing, window and gutter replacement, and paint/trim work. In addition, an initial amount of upgrade work is required for both plumbing and electrical systems. Cost estimates for this segment are \$270,000.

4. Based on an immediate need for a secure perimeter and maintenance and rehabilitation work for the Scattergood-Thorne grounds and structure, it is requested that \$400,000 be provided as an unfunded requirement.



SUBJECT: Unfunded Request - Scattergood-Thorne

OL/FMD (17 July 87)

Distribution:

- Orig To be returned OL/FMD (Official)
  - $\tilde{2}$  DDA
  - 1 OL Files
  - 1 OL/B&F Files
  - 1 OL/FMD Chrono

2

SECRET

25X1