

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

IN 95826 BARON 0039 SECRET

PAGE 2

THE VERTICAL REFERENCE SYSTEM (NAVY RESPONSIBILITY) PREVENTED CHECKOUT OF DOPPLER NAV SYSTEM. AFTER SEVERAL FAILURES AND APPROXIMATELY TWO WEEKS DELAY THE APN-67 VERTICAL GYRO SYSTEM REPLACED WITH AN MD-1. DOPPLER CAL FLIGHT ACCOMPLISHED WITH EXCELLENT RESULTS. PROBLEMS CONTINUE WITH DALMO VICTOR SYSTEM. INERTIAL PLATFORM RETURNED TO VENDOR FOR CORRECTION OF PROBLEMS. THE PLATFORM RETURNED THIS CONTRACTOR 16 DECEMBER AND IMMEDIATELY INSTALLED IN AIRCHAFT. UNABLE LAUNCH FLIGHT 16 DECEMBER DUE WEATHER. S E C R E T TOR 191707Z DEC 66

SECRET